

**S E C R E T**

1		4
2		5
3		6

# PRIORITY

**PRIORITY**

IN 49243

TOR: 2242Z 19 SEPT 62

25X1  
25X1

## INFO

**CITE**

25X1

1. T-105 CARTS BEING MODIFIED THIS WEEK. NEW LOAD CONTROL VALVE BEING INSTALLED TODAY. NEW FILTER KITS ARRIVE TOMORROW WITH AIRESEARCH TECH REP FOR INSTALLATION.

2. J-58 ENGINE EXPERIENCED A FADE-OUT ON ACCELERATION AGAIN TODAY-INDICATING THAT WE STILL HAVE FUEL CONTROL PROBLEMS. FUEL CONTROL VALVE BEING DISASSEMBLED FOR INSPECTION AND REPAIR THIS AFTERNOON. ENGINE WILL BE RUN AGAIN TONIGHT BUT PROGRAM IS SET BACK ANOTHER 24 HOURS. THE AFTERBURNER NOZZLE INSTABILITY HAS APPARENTLY BEEN SOLVED. 2

END OF MESSAGE

or deferred

GROUP I  
EXCLUDING FROM AUTOMATIC  
DOWNGRADING AND  
DECLASSIFICATION

**S E C R E T**